



**Certificate of Conformity of Factory Production Control**  
**No.: 0094/CPR/ MAD/20170163 ENG Schedule**

Manufacturer: **INDUSTRIAL MOREYPI, S.A.**  
 Avda. Agricultura, 13, Polígono de Bankuni6n II– 33211 –  
 Tremañes – Gij6n – Asturias – Spain

<b>Manufacturing plant (s)</b>	Calle Bazán, parcela 82-84 P.I. Bankunion I - 33211 Tremanes-Gij6n – Asturias, Espaa	
<b>Product</b>	<b>Product standard (s)</b>	
Fabricated Steel components for use in Building & Construction	EN 1090-1:2009+A1:2011 EN 1090-2: 2018	
<b>Production Range</b>		
Cutting, forming, drilling, welding, corrosion protection		
<b>Exclusions</b>		
Design and mechanical fastening		
<b>Parent material group (ISO/TR 15608):</b>	<b>Welding process (ISO 4063)</b>	
Group (s): 1 ( Yield Strenght $\leq 355$ N/mm <sup>2</sup> )	<b>111-136-141</b>	
Thickness: up to 40 mm		
<b>CE marking method: 3a</b>	<b>Execution class:</b>	<b>EXC-4</b>

Schedule Issue: 03

Date of Schedule Issue: 17 November 2023

LRQA Inspection Iberia, S.A. Notified Body 0094

Teresa Souto LRQA Inspection Iberia Technical Manager



LRQA Inspection Iberia, S.A. is a company registered in the R. M. de Madrid, in Volume 5218 general, 4358, of Section Sec. 3.ª of the Companies Book, folio 133 sheet n 41397, inscription. 1.ª C.I.F. - A28591287 - Registered office C/Princesa 29, 1. 28008 Madrid. A subsidiary of LRQA Group Limited.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.